


Therma-Wave Floating Puck Upgrade for Opti-Probe OP5xxx and OP7xxx



Floating Puck Upgrade for OP5xxx and OP7xxx

P/N 290300-12 or P/N 59-084737

On Opti-Probe OP5xxx and OP7xxx there are chronic problems with Stage Docking

- Unbalanced and uneven pulling down of opticsplate
- Thereby higher consumption of diaphragm (P/N 290300-12 or P/N 59-084737)
- Rough and uneven docking may lead to instability
- Breakage of docking cable

The „Floating Puck upgrade kit“ includes 4 pcs Aluminium Pucks, which replace the original, screwed in pucks of the vibration cylinder.

Proven Advantages:

1. Improvement of docking, becomes more reliable.
2. Balanced and even pulling down of opticsplate
3. No consumption of diaphragm resulting in lower CoO
4. Higher Uptime

It takes about 8h to replace the docking pucks.

Cost for 1 set Floating Puck Upgrade for OP5xxx and OP7xxx:

€ 1.450.- plus installation

Please contact daniel.grau@teltec.com for details. Page 1 of 1